

Grenzfrequenz

```
.MEAS AC tmp max MAG(V(out)) ;Maximum in tmp speichern  
.MEAS AC meas_3db WHEN MAG(V(out))=tmp/SQRT(2)
```